

Taken 1945.

Park Drain Outfall into  
Cross Drain.



4'-0" fall in 1 chain  
caused by ice & snow.

The water level in Park Drain was  
only 12" below land, although there  
was a 4'-0" fall at the outfall, and  
this level was maintained for  
2 to 3 days.

South Drove Drain at Crowland  
Common Outfall.



In Flood!